

Oil Field Environmental Incident Summary

Incident: 20150516131045 **Date/Time of Notice:** 05/16/2015 13:10

Responsible Party: CONTINENTAL RESOURCES, INC.

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: LOKKEN 1-2H

Field Name: STONEVIEW

Well File #: 17675

Date Incident: 5/16/2015 **Time Incident:** 06:00

Facility ID Number:

County: WILLIAMS

Twp: 159

Rng: 95

Sec: 2

Qtr:

Location Description:

Submitted By: Patrick Skillestad

Received By:

Contact Person: Patrick Skillestad
PO BOX 268870
OKLAHOMA CITY, OK 73126

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	2	Barrels	2	Barrels		
Brine	2	Barrels	2	Barrels		

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

30 ft x 60 ft

Potential Environmental Impacts:

Location soil

Action Taken or Planned:

Standing fluid was sucked up and contaminated soil was removed.

Wastes Disposal Location: Solids to Prairie Disposal and liquids to SV MacGregor.

Agencies Involved:

Updates

Date: 5/18/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.